EMERGENCY PROCEDURES S/N 18268164 1982 N9987H Cessna 182R

Bold-faced type are immediate action items which should be committed to memory.

Engine Failure During Takeoff

Eligilie Fallule Durilly Takeon		
Roll		
	ThrottleIDLE	
2.	Brakes APPLY	
3.	Wing Flaps RETRACT	
4.	MixtureIDLE CUT OFF	
5.	Ignition SwitchOFF	
6.	Master SwitchOFF	
Engine Failure Immediately		
After Takeoff		

	13 MAO (i laps op)	
	70 KIAS (Flaps Down)	
2.	MixtureIDLE CUT	OFF
3.	Fuel Selector	OFF

1. Airspeed

75 KIAS (Flans IIn)

4. IgnitionOFF5. Wing Flaps. AS REQUIRED (Full Recommended)

6. Master Switch OFF

Engine Failure During Flight (Restart)

1.	Airspeed 75 KIAS	
2.	Carb HeatON	
3.	Fuel Selector BOTH	
4.	MixtureRICH	
5.	Ignition BOTH	
	(or START if propeller is	
	stopped)	
6.	Primer IN & LOCKED	

Forced Landing w/o Engine Power

1. <i>F</i>	Airspeed75	KIAS (Flaps Up)
		IAS (Flaps Down)
2. N	Mixture	IDLE CUT OFF
3. F	Fuel Selector	OFF
		OFF
5. V	Wing Flaps	AS REQUIRED
6. (Full Recomme	nded)
7. N	Master Switch	OFF
8. E	Doors	UNLATCH
9. p	orior to Touchd	own
10.	Touchdown	. Slightly Tail Low
11.	Brakes	APPLY HEAVILY

Precautionary Landing With Engine Power

1.	Airspeed75 KIAS
2.	Wing Flaps 20
3.	Select Field(Perform
	Fly Over Inspection)
4.	Electrical Switches 0FF
5.	Flaps Full on Final Approach
6.	Airspeed70 KIAS
7.	Avionics & Master Switches OFI
8.	DoorsUNLATCHED
	Prior To Touchdown
9.	Touchdown Slightly Tail Lov

Engine Fire During Start

١.	Continue Cranking Engine
2.	If Engine Starts:Power
	1700 RPM for a few minutes

10. Ignition Switch.....OFF

11. Brakes..... APPLY HEAVILY

- 3. Engine Shutdown and Inspect If Engine Fails to Start:
- 4. Throttle..... FULL OPEN 5. Mixture IDLE CUT OFF
- 6. Cranking......CONTINUE
- 7. Fire Extinguisher OBTAIN
- 8. Master/Ignition/FuelOFF

9. Fire	EXTINGUISH
	INSPECT

Engine Fire in Flight

1.	Mixture IDLE CUT	OFF
2.	Fuel Selector	OFF
3.	Master Switch	OFF
4.	Cabin Heat & Air	OFF
	(Except Overhead Vents)	
_	A 400	1/1/6

- 6. Forced Landing w/o Engine Power EXECUTE

Electrical Fire in Flight

1. Master Switch	OFF
(Leave Ignition On)	
2. Avionics Power Switch	OFF

- 3. All Other Switches (Except Ignition)OFF
- 4. Vents/Cabin Air/Heat CLOSED
- 5. Extinguisher ACTIVATE

Warning

After discharging an extinguisher within a closed cabin, ventilate the cabin.

If fire appears out and electrical power is necessary for continuance of flight:

- 6. Master SwitchON7. Circuit BreakersCheck for Faulty circuit (Do Not Reset)
- 8. Radio SwitchesOFF
- 9. Avionics Power Switch......ON

- 10. Radio/Electrical Switches ...ON one at a time w/ delay after each until short is localized.
- 11. Vents/Cabin Air/Heat....OPEN when it is ascertained that fire is completely extinguished.

Cabin Fire

- 1. Master Switch OFF (Leave Ignition On)
- 2. Vents/Cabin Air/HeatCLOSED
- 3. Fire Extinguisher.. ACTIVATE

Warning

After discharging an extinguisher within a closed cabin, ventilate the cabin.

4. Land . As soon as possible and INSPECT damage

Wing Fire

Navigation Lights.....OFF
 Strobe Lights.....OFF
 Pitot HeatOFF

Note

Sideslip to keep flames away from the fuel tank and cabin, and land as soon as possible using flaps only as required for final approach and touchdown.



Icing

- 1. Pitot HeatON
- 2. Turn back or change altitude to obtain an outside air temp that is less conducive to icing.
- Pull cabin heat control to full out and rotate defroster control clockwise to obtain maximum defroster airflow.
- 4. Increase Engine Speed to minimize ice build-up on propeller blades
- 5. Watch for signs of carburetor air filter ice and apply carburetor heat as required. An unexplained loss of manifold pressure could be caused by carburetor ice or air intake filter ice. Lean the mixture if carburetor heat is used continuously.
- Plan a landing at the nearest airport. With an extremely rapid ice build-up, select a suitable "off airport" landing site.
- With ice accumulation of ¼ inch or more on the wing leading edges, be prepared for significantly higher stall speed.
- 8. Leave wing flaps retracted. With a severe ice build-up on the horizontal tail, the change in wing wake airflow direction caused by wing flap extension could result in a loss of elevator effectiveness.
- Open left window and if practical scrape ice from a portion of the windshield for visibility in landing approach.

- Perform landing approach using a forward slip, if necessary, for, improved visibility.
- 11. Approach at 80 to 90 KIAS depending upon the amount of accumulation.
- 12. Perform a landing in level attitude.

Ditching

- 1. Radio..... Transmit **MAYDAY** on 121.5 giving location and intentions and squawk 7700.
- 2. Heavy Objects.....SECURE Or Jettison.
- 3. Flaps 20° to 40°
- 4. Power..... Est. a 300 FPM descent at 65 KIAS.
- Approach
 High winds, heavy seas Into the Wind.
 Light winds, heavy swells.......
 Parallel to swells.

Note

If no power is available, approach at 75 KIAS with flaps up or at 70 KIAS with 10° flaps

- 6. Cabin DoorsUNLATCH
- 7. Touchdown......LEVEL attitude at established descent rate.
- 8. Face Cushion at touchdown with folded coat.
- AirplaneEvacuate through Cabin doors. If necessary, open window and flood cabin to equalize pressure so doors can be opened.
- 10. Life vests and raft INFLATE

For all other
Emergency
Abnormal
Procedures.
See the
POH
Section 3.

Airspeeds for Emergency Operations

Engine Failure After Takeoff:

Wing Flaps Up -- 75 KIAS Wing Flaps Down -- 70 KIAS

Maneuvering Speed:

Maximum Glide:

3100 Lbs -- 111 KIAS 2600 Lbs -- 102 KIAS 2000 Lbs -- 88 KIAS

3100 Lbs - 76 KIAS 2600 Lbs - 70 KIAS

2000 Lbs - 61 KIAS

Precautionary Landing With Engine Power – 70 KIAS

Landing Without Engine Power:

Wing Flaps Up - 75 KIAS Wing Flaps Down - 70 KIAS

This checklist is a guide to coordinate Pilot Operating Handbook and STC data applicable to this particular aircraft only. The applicable Pilot Operating Handbook and STC installations remain the official documentation for this aircraft.

The pilot in command is responsible for complying with all items in the Pilot Operating Handbook and applicable STCs.

I certify this checklist has been reviewed for accuracy.

For the

1/06/2006

Wing Director of Maintenance

Date